

# NEC *Tech Tip*

**Date:** 08/10/2004

**Number:** NEC0051

System	Software
DS1000	03.03.00 and Higher

**Title:** DS1000 Program 1001-ANI/DNIS Entry Disables Caller ID

---

With the DS1000 using software 03.03.00 and higher, if an entry is made in **Program 1001 - Trunk Port Description, ANI/DNIS** (even though T1 is not supported by the DS1000), Caller ID will be disabled.

Future software will be changed so that this option will ignore all non-T1/E1 trunks.